MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR

Date: 6-26-09


Crew: Taylor

Name: 17021505

SEC. 15 TWN. 17_N RNG. 2_E

SECTION CORNER RECORD

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR



This corner is not referenced in the Pike Township Legal Survey Book. Corner referenced by Monroe on 6/8/1960 and called a pipe. 8/9/73 Wilcoxen called a RR spike 2'W of edge of pavement 2" down. 4/10/75 Miller called a RR spike. Corner was excavated on 9/29/81 by Wilcoxen and a 1" iron pipe was found 5" down. A RR spike was also found 5" down, but was located 0.15' N and 0.05' W of the 1" pipe. The 1" pipe was re-set and a RR spike was set in the pipe. Corner was excavated by Kiste on 8/21/1995 and a PK nail was found at surface. A RR spike inside a 1" pipe was found 4" down. No stone was found. A #205 cast iron Harrison Monument was set in position as the corner, 4/18/2000 Wilcoxen retied, 2/15/05 Wilcoxen retied, 6/26/09 Greene retied,

3.

REF.	DISTANCE	DESCRIPTION
1.	67.61'	PK nail W PwP #55-192 14" up
2.	38.70'	PK nail SW wooden fence post 24" up
3.	163.14'	PK nail W PwP #54-192 30" up
4.	7' +/-	Due W to C/L of Moore Rd
5.	31.54'	RR spike S twin ash 30" up

THIS CORNER POSITION REPRESENTS A "TITLE" CORNER AND MAY NOT NECESSARILY REPRESENT THE POSITION BASED ON RECORD CORNERS